

General Information

Registration No.	PP-2BW-0934	Transmission	Automatic
Chassis No.	MHKAA1BC60J004634	Model Year	2024
Engine No.	PP-2BW-0934	Colour	White
Make	Toyota	Location	BTB
Model	Wigo	Fuel Type	Petrol
CC	undefined	Mileage	44,824
Grade	Great	Expiry Inspection License	
Type of Body	HATCHBACK	Expiry - Insurance	

Overall Evaluation

B+
Great

Interior

B+
Great

Frame


B+
Great

Exterior


B
Good

Functional

B+
Great



Damage Illustration - Interior



Damage Illustration - Exterior

Inspector Note

Wigo 024 PP-2BW-0934 44,824km Service regular Inquiry trade in not sure Raize or YC yet Scratch front bumper RH medium () Scratch front door RH medium () Scratch rear fender RH small Scratch rear bumper and dent rear and front door LH Scratch front bumper Scratch hood () Stone chip glass windshield Cleaning 1 EST RC \$500

Inspection Date	September, 28 2026	Vehicle Type	Toyota HATCHBACK undefined 2024
Location	BTB	Registration no	PP-2BW-0934

Photo

Exterior Front



Exterior Front Left



Exterior Front Right



Engine



Registered Document



Odometer



Interior Front Left



Interior Rear Left



Interior From Rear Seat To Front



Exterior Rear Left



Exterior Rear Right



Exterior Rear



Inspection Date	September, 28 2026	Vehicle Type	Toyota HATCHBACK undefined 2024
Location	BTB	Registration no	PP-2BW-0934

Rear Back Door Room Trunk Hood



Tool Kits



Interior Rear Right



Interior Front Right



Inspection Date	September, 28 2026	Vehicle Type	Toyota HATCHBACK undefined 2024
Location	BTB	Registration no	PP-2BW-0934

Interior

B+
Great



Illustration Damage

Damage Symbol:

a	Worn / Scrath / Cut / Crack / Peel / Fray
d	Worked / Loose / Deformed / Traces of Adhesive Tape / Grime / Repair Mark / Sunburn / Crinkle
k	Animal Hair
s	Smell
t	Cigarette Burns
x	Missing / Partially Missing
y	Grime

Damage level:

1	Minimal	3	Medium
2	Small	4	Large

Area	Parts Name	Damage Name	Damage Level
-	Overall Interior	-	-
1	Ceiling	-	-
	Switchs	-	-
	Room Mirror	-	-
	(L) Sunvisor	-	-
	(R) Sunvisor	-	-
	Sunglass Holder	-	-
	Front Room Lamp	-	-
	Rear Room Lamp	-	-
2	Dashboard	-	-
	Glove Box	-	-
	Instrument Panel	-	-
	Steering Wheel	-	-

Inspection Date	September, 28 2026	Vehicle Type	Toyota HATCHBACK undefined 2024
Location	BTB	Registration no	PP-2BW-0934

Area	Parts Name	Damage Name	Damage Level
3	Knobs	-	-
	Console	-	-
	Switchs	-	-
	Vents	-	-
	Display	-	-
	Audio System	-	-
4	Carpet	-	-
	(R) Front Floor Lag	-	-
	(L) Front Floor Lag	-	-
	Lag Other	-	-
5	(R) Front Seat	-	-
	(R) Front Seat Knobs	-	-
	(R) Front Seat belt	-	-
6	(R) Front Trim	-	-
	(R) Rear Trim	-	-
	Trim Other	-	-
	Switchs	-	-
7	Rear Seat	-	-
	Trim Other	-	-
	Seat belt Other	-	-
8	Trunk Room	-	-
9	(L) Front Seat	-	-
	(L) Front Seat Knobs	-	-
	(L) Front Seat belt	-	-
10	(L) Front Trim	-	-
	(L) Rear Trim	-	-
	Trim Other	-	-
	Switchs	-	-

Inspection Date	September, 28 2026	Vehicle Type	Toyota HATCHBACK undefined 2024
Location	BTB	Registration no	PP-2BW-0934

Coating Thickness

Bonnet  	Left Front Fender  	Left Front Door  		Left Rear Door  	Left Rear Fender  	Roof  	Trunk  
	Right Front Fender  	Right Front Door  		Right Rear Door  	Right Rear Fender  		

Panel Name	Panel Result	Panel Name	Panel Result
1. Bonnet - Left - Center - Right	Normal	7. Left Rear Fender - Left - Center - Right	Normal
2. Trunk - Left - Center - Right	Normal	8. Right Front Fender - Left - Center - Right	Normal
3. Roof - Left - Center - Right	Normal	9. Right Front Door - Left - Center - Right	Normal
4. Left Front Fender - Left - Center - Right	Normal	10. Right Rear Door - Left - Center - Right	Normal
5. Left Front Door - Left - Center - Right	Normal	11. Right Rear Fender - Left - Center - Right	Normal
6. Left Rear Door - Left - Center - Right	Normal		

Inspection Date	September, 28 2026	Vehicle Type	Toyota HATCHBACK undefined 2024
Location	BTB	Registration no	PP-2BW-0934

Frame


B+
Great

Parts Name	Damage Score
Front Cross Member Support	Normal
Right Front Inside Panel (Front Side)	Normal
Left Front Inside Panel (Front Side)	Normal
Right Front Inside (Rear Side)	Normal
Left Front Inside (Rear Side)	Normal
Left Front Pillar	Normal
Right Front Pillar	Normal
Right Center Pillar	Normal
Left Center Pillar	Normal
Center Floor Panel	Normal
Under Spare Box	Normal
Rear Side Member & Trunk Room Floor	Normal
Left Tyre House	Normal
Right Tyre House	Normal
Front Floor and Side Member	Normal
Front Floor Panel and Front Frame	Normal
Rear Frame	Normal

Inspection Date	September, 28 2026	Vehicle Type	Toyota HATCHBACK undefined 2024
Location	BTB	Registration no	PP-2BW-0934

Exterior

B
Good



Damage Symbol:

A	Scratch / Peeled / Crack / Cut
B	Modified
C	Corrosion
G	Stone Chip
P	Faded (Color,Gross)
S	Rust
U	Dent / Bent
X	Stuck
Y	Crack / Gap / Cap / Damaged

Damage level:

1	Minimal	3	Medium
2	Small	4	Large

Illustration Damage

Area	Parts Name	Damage Name	Damage Level
0	Overall Exterior	-	-
1	Supplemental Mirror	-	-
	(R) Front Tyre	-	-
	(R) Front Fender	Scratch	Medium
	Molding	-	-
	(R) Front Wheel	-	-
	Wheel Cover	-	-
	(R) Side Window	-	-
2	(R) Mirror	-	-
	(R) Front Door	Scratch	Medium
	Molding	-	-
	(R) Rear Door	-	-

Inspection Date		September, 28 2026	Vehicle Type		Toyota HATCHBACK undefined 2024
Location		BTB	Registration no		PP-2BW-0934
Area	Parts Name	Damage Name		Damage Level	
4	Molding	-		-	
5	(R) Rear Tyre	-		-	
	(R) Rear Corner Panel	-		-	
	(R) Rear Fender	Scratch		Small	
	Molding	-		-	
	(R) Rear Wheel	-		-	
	Wheel Cover	-		-	
6	(R) Center Panel	-		-	
	(R) Step	-		-	
	In-panel	-		-	
	Side Spoiler	-		-	
7	(L) Front Tyre	-		-	
	(L) Front Fender	-		-	
	Molding	-		-	
	(L) Front Wheel	-		-	
	Wheel Cover	-		-	
8	(L) Side Window	-		-	
	(L) Mirror	-		-	
	(L) Front Door	Scratch & Dent		Small	
	Molding	-		-	
10	(L) Rear Door	Scratch & Dent		Small	
	Molding	-		-	
11	(L) Rear Tyre	-		-	
	(L) Rear Corner Panel	-		-	
	(L) Rear Fender	-		-	
	Molding	-		-	
	(L) Rear Wheel	-		-	
	Wheel Cover	-		-	
12	(L) Center Panel	-		-	

Inspection Date		September, 28 2026	Vehicle Type		Toyota HATCHBACK undefined 2024
Location		BTB	Registration no		PP-2BW-0934
Area	Parts Name	Damage Name		Damage Level	
12	(L) Step	-		-	
	In-panel	-		-	
	Side Spoiler	-		-	
13	Front Panel	-		-	
	Member (Bolted)	-		-	
	Front Bumper	Scratch		Small	
	Grille	-		-	
	Lamps	-		-	
14	Bonnet	Scratch		Small	
	Headlight	-		-	
15	Roof	-		-	
	Front Windshield	Scratch, Stone chip		Small	
	Rear Windshield	-		-	
	Roof Spoiler	-		-	
	Molding	-		-	
16	Trunk Hood, Rear Gate	-		-	
	Antennae	-		-	
17	Rear End Panel	-		-	
	Muffler and Undercarriage Parts	-		-	
	Rear Bumper	Scratch		Small	
	Lamps	-		-	
	Panels	-		-	

Inspection Date	September, 28 2026	Vehicle Type	Toyota HATCHBACK undefined 2024
Location	BTB	Registration no	PP-2BW-0934

Functional

B+
Great

Parts Name	Damage Level Name
Retractable Mirror	Okay
All Warning Lamps Illuminate	Okay
Panel	Okay
Meter	Okay
Power Window (each)	Okay
Door Lock	Okay
Sun Roof	Okay
Power Seat	Okay
Power Steering Turning	Okay
Air Conditioner	Okay
12V Battery Condition	Okay
Smart Entry System	Okay
Remote Boot Release	Okay
Push-button Start	Okay
Audio, Radio	Okay
Reverse Camera	Okay
Parking Brake	Okay
Brake Pedal	Okay
Turn Signal	Okay
Hazard Flasher	Okay
Wipers	Okay
Washers	Okay
Horn	Okay
Seat Belts	Okay

Inspection Date	September, 28 2026	Vehicle Type	Toyota HATCHBACK undefined 2024
Location	BTB	Registration no	PP-2BW-0934

Parts Name	Damage Level Name
------------	-------------------

Spare Keys & Remote Controls	Okay
Parking sensor rear	Okay
Vehicle Jack and Tool Kit	Okay
Spare Tyre	Okay
Tyre Repair Kit	Okay

Mechanical

Parts Name	Damage Level Name
------------	-------------------

Engine coolant level	Okay
Radiator Fan	Okay
Radiator Core & Tanks	Okay
Coolant lines	Okay
Radiator Water Pump	Okay
Air Filter	Okay
Drive Belts	Okay
Oil Leaks	Okay
Engine Mounts	Okay
Engine Oil level	Okay
Clutch Fluid level	Okay
Brake Fluid level	Okay
Power Steering Pump	Okay
Power Steering Fluid level	Okay
Engine Starts Properly	Okay
Engine Accelerates Smoothly	Okay
Gear Changing is Smooth	Okay

Inspection Date	September, 28 2026	Vehicle Type	Toyota HATCHBACK undefined 2024
Location	BTB	Registration no	PP-2BW-0934

Appendix - Damage Photos

(R) Front Fender - Scratch



(R) Front Door - Scratch



(R) Rear Fender - Scratch



Rear Bumper - Scratch



(L) Rear Door - Scratch & Dent



(L) Front Door - Scratch & Dent



Inspection Date	September, 28 2026	Vehicle Type	Toyota HATCHBACK undefined 2024
Location	BTB	Registration no	PP-2BW-0934



Front Windshield - Scratch, Stone chip



Inspection Date	September, 28 2026	Vehicle Type	Toyota HATCHBACK undefined 2024
Location	BTB	Registration no	PP-2BW-0934

Disclaimer

This Grading Report is intended to record the general condition of the vehicle within the range of the set scope. This is not a comprehensive inspection guarantee. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

